			Customer			
		~ °	Address			
Subi	Toe	h III	Phone			
	2126		FIIUIIE			
20727 High Dese	ert Ct Suite 2				tor Comis	
Bend, OR 97701		Fuel Injector Service				
(541) 213-8549		Diagnostic Report				
subietech@gmai	I.com					
				Test Dress		
BEFORE CLE		On any Dattern			ure >> 4 bar	O a margareta
Injector #	Leak Test	Spray Pattern	M/S - RPM	Flow Rate	Inductance	Comments
	ok ok	correct	3.0 @2500	15ML	12.7	
	ok ok	correct	3.0 @2500	14ML 15ML	12.8	
	ok	correct	3.0 @2500 3.0 @2500	15ML	12.9	
	ok		3.0 @2500 3.0 @2500	15ML	12.8	
	ok	correct	3.0 @2500	15ML	12.9	
0		Conect	3.0 @2500		12.9	
AFTER CLEANING			Test Pressure >> 4 bar			
Injector #	Leak Test	Spray Pattern	M/S - RPM	Flow Rate	Inductance	Comments
	ok	correct	3.0 @2500	15ML	12.8	
	ok	correct	3.0 @2500	15ML	12.8	
	ok	correct	3.0 @2500	15ML	12.9	
	ok	correct	3.0 @2500	15ML	12.8	
	ok	correct	3.0 @2500	15ML	12.8	
6	ok	correct	3.0 @2500	15ML	12.9	
_						
SERVICE ITE	MS	Part #	Quantity	Each	Total	Notes
Pintle Cap						
Filler Baskets						
O-Ring Seal Top						
O-Ring Seal Bott	om					
Spacer						
Rubber Head Se	al					
			1			
Clamp Ring Seal						
Clamp Ring Seal Injector Hose						
· -				Labor		Subietech HQ does not warranty cleaned injectors as no internal parts are replaced during